

Title	Lead in Dust Wipes
Specimen Requirements	See ASTM Practice E1728, NIOSH Method 9100, and/or pertinent HUD publications for specific sampling requirements.
Sampling Materials	<p>Use ASTM specification 1792 E dust wipe sampling media.</p> <p>Submit samples in re-sealable plastic bags.</p>
Procedural Notes	<p>There are at least five general requirements possessed by a good group of dust wipe samples:</p> <ol style="list-style-type: none"> A group of dust wipe samples contains a field blank and dust wipe samples. (A field blank is a dust wipe opened at the sampling location then stored and submitted in the same type container as the dust wipe samples.) ALWAYS submit a field blank with each sample group. ALWAYS record the sampled area for each dust wipe sample; either linear dimensions or the calculated area are acceptable. Dust wipes should be free from copious amounts of paint chips (as from a deteriorated window trough). One sample is one dust wipe: DO NOT composite samples (i.e. submit multiple wipes from the same area in one container). Each sample is identified by a number unique in its sample group or location, especially if paint chip or soil samples are submitted also. Simple numbering is best. <p>Include a completed Dust Wipe Sample Submission Form. Blank forms may be obtained from the laboratory as paper or electronic originals (specify Word or PDF format with the request for electronic blanks.)</p>
Shipping Instructions	Place bag(s) containing sample(s) in an appropriate shipping container and ship to: ISDH Laboratories, Indoor Air Laboratory, 550 W. 16th Street, Suite B, Indianapolis, IN 46202
Reporting and TAT	